


d	m	h	s	e	dk	
M3	2,4	7	5,5	6,01	5,5	5,5
M4	3,2	8	7	7,66	6,5	7,0
M5	4,0	10	8	8,79	7,5	8,0
M6	5,0	12	10	11,05	9,5	10,0
M8	6,5	15	13	14,38	12,5	13,0
M10	8,0	18	17	18,90	16,0	17,0
M12	10,0	22	19	21,10	18,0	19,0
M14	11,0	25	22	24,49	21,0	22,0
M16	13,0	28	24	26,75	23,0	24,0
M18	15,0	32	27	30,14	26,0	27,0
M20	16,0	34	30	33,53	28,0	30,0
M24	19,0	42	36	39,98	34,0	36,0
M27	20,0	47	41	47,30	40,0	41,0
M30	24,0	52	46	52,00	42,0	46,0